

Retrotec Gauge and Fan Compatibility Chart

Fantype	Subtype	DM2	DM32	DM32X	Remark:
1000		Y	Y	Y	
2000	2201/2202 FanTop	Y	N*	N*	This fantop model has one speed control port. Requires prior resistor modification to be DM32 or DM32X compatible. No longer serviceable. Requires replacement with a newer style fan.
2000	2350 FanTop	Y	Y	Y	This fantop style has two speed control ports. DM32 and DM32X compatible, but no longer serviceable. Safest option is to upgrade to a newer fan.
3000	3300 auto-switching Drive	Y	N*	N*	This drive model has one speed control port. Requires prior resistor modification to be DM32 or DM32X compatible. No longer serviceable, Recommend upgrade to 3350 drive.
	3350 Drive	Y	Y	Y	
4000		N	Y	Y	
5000		N	Y	Y	
6000		N	Y	Y	
7000		N	N	Y	
200	Square Metal Shell 200 Series	Y	N	N	No longer serviceable. Required upgrade to newer style fan.
200	Plastic Shell 200 Series	Y	Y	Y	Recommend upgrade. Fan repairs not possible.
300		N	Y	Y	
400		N	Y	Y	Needs to have 20A or 30A sensor.
500		N	Y	Y	Needs latest DM32 firmware

\*If fantop or drive has received modification by Retrotec in the past, it may be DM32(X) compatible. By default, not compatible.